

Recreational Waters Bacterial Monitoring Program - Swan and Canning Rivers - Site Status Overview: 2006-2012

Site Code	LGA	Site Name	Result Years	No. samples	95th %tile	MAC	1 sample Trigger Level 99th %tile	2 samples in-a-row Trigger Level 90th %tile	SAC	SIC Factor	SIC Status Comments	Provisional Classification	Provisional Web Colour	Min No. LGA samples Rqd 2012-2013
EV3/522	Bassendean	Sandy Beach Reserve	2007-2012	68	390	C	3806	283	Moderate	Rainfall	Collect 10 rainfall (24-48hrs) samples	Poor	Red	12
EV3/548	Bassendean	Point Reserve (Nth Jetty)	2011-2012	20	780	D	758	216	High - F/up	Stormwater	Provide DoH stormwater drain monitoring results	Very Poor	Red	12
EV3/523	Bayswater	Hind Reserve (Garratt Rd - Jetty)	2007-2012	71	65	B	102	43	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Green	12
EV3/541	Bayswater	East St Maylands Yacht Club	2007-2012	75	75	B	138	46	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Green	12
EV3/517	Belmont	Garvey Park (Fauntleroy Ave)	2007-2012	70	250	C	2045	117	Moderate	Rainfall	Collect 10 rainfall (24-48hrs) samples	Poor	Red	12
EV3/538	Belmont	Belmont Park Beach	2007-2012	68	115	B	151	58	Moderate	Rainfall	Collect 10 rainfall (24-48hrs) samples	Good	Green	12
EV3/539	Belmont	Cracknell Park (Riversdale Rd)	2007-2012	67	55	B	88	41	Moderate	Rainfall	Collect 10 rainfall (24-48hrs) samples	Good	Green	12
EV3/542	Canning	Shelly Beach (Near Drain)	2007-2012	71	80	B	14471	46	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Green	12
EV3/547	Canning	Clontarf Bay (Cadets)	2010-2012	40	170	B	243	75	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Green	12
EV3/545	East Fremantle	Preston Point - John Tonkin Park	2006-2012	66	2	A	20	14	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Green	5
EV3/505	Melville	Bicton Baths	2007-2012	69	40	A	1281	31	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Green	12
EV3/507	Melville	Cunningham St (Applecross)	2007-2012	69	36	A	473	10	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Green	12
EV3/532	Melville	Point Walter (Kiosk)	2007-2012	69	85	B	187	49	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Green	12
EV3/533	Melville	Point Walter (Boat Ramps)	2007-2012	69	18	A	54	23	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Green	12
EV3/534	Melville	Waylen Bay (Scout Hall)	2007-2012	68	4	A	30	14	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Green	5
EV3/540	Melville	Deep Water Point Beach (Near Jetty)	2006-2011	68	7	A	37	17	Moderate	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	5
EV3/544	Mosman Park	Johnston Street - Hill Tce Beach	2007-2012	76	32	A	107	10	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Green	12

Recreational Waters Bacterial Monitoring Program - Swan and Canning Rivers - Site Status Overview: 2006-2012

Site Code	LGA	Site Name	Result Years	No. samples	95th %tile	MAC	1 sample Trigger Level 99th %tile	2 samples in-a-row Trigger Level 90th %tile	SAC	SIC Factor	SIC Status Comments	Provisional Classification	Provisional Web Colour	Min No. LGA samples Rqd 2012-2013
EV3/503	Peppermint Grove	Keane St Beach (50M S Irvine)	2007-2012	77	75	B	142	45	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Green	12
EV3/511	South Perth	Como Beach Jetty	2006-2012	83	2	A	15	11	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Green	5
EV3/512	South Perth	Narrows Bridge	2007-2012	72	140	B	4313	59	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Green	12
EV3/513	South Perth	Coode St South Perth	2007-2012	73	195	B	290	84	Moderate	Rainfall	Collect 10 rainfall (24-48hrs) samples	Good	Green	12
EV3/536	South Perth	Como Beach South	2007-2012	73	75	B	266	38	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Green	12
EV3/537	South Perth	Como Beach North	2007-2012	73	195	B	975	104	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Green	12
EV3/546	South Perth	Esplanade Beach	2009-2012	69	90	B	129	50	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Green	12
EV3/528	Subiaco	Hackett Dve Crawley (Kiosk, Jetty)	2007-2012	70	85	B	158	49	Moderate	Rainfall	Collect 10 rainfall (24-48hrs) samples	Good	Green	12
EV3/530	Subiaco	Hackett Dve Crawley (Tree)	2007-2012	70	60	B	108	41	Moderate	Rainfall	Collect 10 rainfall (24-48hrs) samples	Good	Green	12
EV3/543	Subiaco	Abrahams Reserve Beach	2007-2012	70	16	A	54	20	Moderate	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	12
EV3/518	Swan	King Meadow Reserve (Helena Rvr)	2007-2012	78	390	C	3642	110	High - F/up	Rainfall	Collect 10 rainfall (24-48hrs) samples	Poor	Red	0
EV3/519	Swan	Ray Marshall Park (First Ave)	2007-2012	93	330	C	24000	139	High - F/up	Rainfall	Collect 10 rainfall (24-48hrs) samples	Poor	Amber	12
EV3/520	Swan	Middle Swan Reserve	2007-2012	114	1650	D	11536	520	High - F/up	Rainfall	Collect 10 rainfall (24-48hrs) samples	Very poor	Red	5